
Contents

Part I Looking at Images

| | |
|--|----|
| 1 Images and Microstructures | 3 |
| 1.1 Images and Microstructures | 3 |
| 1.2 Image Analysis | 6 |
| 1.2.1 Direct Image Analysis | 8 |
| 1.2.2 Analysis of Image Segments | 9 |
| 1.2.3 Analysis of Best-fit Ellipses | 10 |
| 1.2.4 Analysis of Digitized Outlines | 10 |
| 1.3 Segmentation | 11 |
| 1.4 Image Models | 12 |
| 2 Acquiring Images | 15 |
| 2.1 Photography | 15 |
| 2.1.1 Field Photography | 15 |
| 2.1.2 Photomacrography | 17 |
| 2.2 Optical Scanners | 19 |
| 2.3 Light Microscopy | 19 |
| 2.3.1 Modes of Polarization Microscopy | 19 |
| 2.3.2 Illumination | 23 |
| 2.3.3 Magnification and Resolution | 24 |
| 2.4 Digital Cameras | 27 |
| 2.5 Electron Microscopy | 29 |
| 2.5.1 Scanning Electron Microscopy (SEM) | 29 |
| 2.5.2 Transmission Electron Microscopy (TEM) | 30 |
| References | 30 |
| 3 Digital Image Processing | 31 |
| 3.1 The Digital Image | 31 |
| 3.1.1 Bit and Bytes | 31 |
| 3.1.2 Gray Values | 33 |
| 3.1.3 Color | 33 |
| 3.2 Stacks | 36 |
| 3.2.1 R-G-B Stacks | 36 |
| 3.2.2 X-Y-Z Stacks | 37 |
| 3.2.3 X-Y-t Stacks | 37 |
| 3.2.4 X-Y- α Stacks | 39 |
| 3.3 Format and Compression | 39 |

| | | |
|--|---|-----------|
| 3.4 | Image SXM | 42 |
| 3.4.1 | Quick Start | 43 |
| 3.4.2 | LUT Window | 43 |
| 3.4.3 | Map Window | 44 |
| 3.4.4 | Info Window | 44 |
| 3.4.5 | Tools | 45 |
| 3.5 | Preparing the Data | 49 |
| 3.5.1 | Exploring the Image | 49 |
| 3.5.2 | Scale and Calibrate | 50 |
| 3.5.3 | Using Color | 51 |
| 3.5.4 | Presenting the Data: The Beauty Case | 53 |
| | References | 56 |
| 4 | Pre-processing | 59 |
| 4.1 | Comparing Images | 59 |
| 4.2 | Background Corrections | 60 |
| 4.2.1 | Direct Background Correction | 61 |
| 4.2.2 | Background Correction Using a Model Background | 64 |
| 4.2.3 | Background Correction Using a Background Image | 64 |
| 4.3 | Re-sizing | 67 |
| 4.3.1 | Nearest Neighbor | 67 |
| 4.3.2 | Bilinear | 68 |
| 4.3.3 | Bicubic | 68 |
| 4.4 | Noise Removal | 72 |
| 4.4.1 | Median Filtering | 72 |
| 4.4.2 | Fourier Filtering | 73 |
| | References | 73 |
| Part II Segmentation: Finding and Defining the Object | | |
| 5 | Segmentation by Point Operations | 77 |
| 5.1 | Look-Up Tables | 77 |
| 5.1.1 | Changing the Contrast: Linear LUTs | 77 |
| 5.1.2 | Non-linear LUTs | 78 |
| 5.1.3 | Special LUTs | 78 |
| 5.2 | Macros | 78 |
| 5.2.1 | Using Macros | 78 |
| 5.2.2 | Lazy LUTs Macro | 80 |
| 5.2.3 | From LUT to Point Operation | 86 |
| 5.3 | Segmentation by Point Operations | 88 |
| 5.3.1 | Segmentation by Thresholding | 90 |
| 5.3.2 | Segmentation by Gray Level Slicing | 90 |
| | References | 94 |
| 6 | Post-processing | 95 |
| 6.1 | Ranking Filters | 95 |
| 6.1.1 | Minimum: Median: Maximum | 95 |
| 6.1.2 | Erosion: Dilation | 97 |
| 6.1.3 | Opening: Closing | 99 |

| | | |
|----------|--|------------|
| 6.2 | Copy Modes | 100 |
| 6.2.1 | Logical Operations | 100 |
| 6.2.2 | Combining Images | 100 |
| 6.3 | Structural Filtering | 102 |
| 6.3.1 | Skeletonization | 102 |
| 6.3.2 | Pruning | 103 |
| 6.3.3 | Watershed | 103 |
| 6.4 | Cleaning Up Bitmaps | 104 |
| 6.5 | Phases, Grains and Boundaries | 106 |
| | References | 111 |
| 7 | Segmentation by Neighborhood Operations | 113 |
| 7.1 | Neighborhood | 113 |
| 7.2 | Averaging Filters | 114 |
| 7.2.1 | Gauss Filters | 116 |
| 7.2.2 | Influence of Shape and Size | 118 |
| 7.3 | Gradient Filters | 119 |
| 7.3.1 | Roberts Cross | 123 |
| 7.3.2 | Sobel Edge Detection | 126 |
| 7.3.3 | Laplace Filters | 128 |
| 7.4 | Edge Detection | 130 |
| | References | 135 |
| 8 | Image Analysis | 137 |
| 8.1 | Image Segments and Best-Fit Ellipses | 137 |
| 8.2 | Deriving Size and Shape Descriptors | 140 |
| 8.3 | Example of Image Analysis | 142 |
| 8.4 | Digitizing Outlines | 144 |
| 8.4.1 | Exporting Segment Boundaries | 146 |
| 8.4.2 | Creating Polygonal Chains | 147 |
| 8.4.3 | The Nature of the Square Grid | 149 |
| 8.4.4 | From Discrete to Continuous | 151 |
| 8.5 | SCASMO | 151 |
| 8.5.1 | How to Run SCASMO | 152 |
| 8.6 | The FABRIC Programs | 156 |
| | References | 156 |
| 9 | Test Images | 157 |
| 9.1 | Numerical Simulations | 157 |
| 9.1.1 | Ellipses | 157 |
| 9.1.2 | Shape and Orientation Distributions | 158 |
| 9.1.3 | Spatial Distributions | 161 |
| 9.2 | Synthetic Particle Fabrics | 161 |
| 9.3 | RANDOM | 163 |
| 9.3.1 | How to Run RANDOM | 164 |
| 9.4 | MONTECARLO | 166 |
| 9.4.1 | Random Sampling | 167 |
| 9.4.2 | How to Run MONTECARLO | 169 |
| | References | 170 |

Part III Measuring Size and Volume

| | | |
|-----------|---|-----|
| 10 | Volume Determinations | 173 |
| 10.1 | Measuring Area Fractions | 173 |
| 10.1.1 | Measuring Areas in Image SXM | 174 |
| 10.1.2 | Counting Pixels | 175 |
| 10.1.3 | Estimating Areas | 177 |
| 10.2 | Estimating Volume Fractions | 177 |
| 10.3 | Determining Errors | 179 |
| 10.3.1 | Errors Associated with Point Counting | 179 |
| 10.3.2 | Errors Associated with Area Measurements | 180 |
| 10.4 | Practical Application | 180 |
| 10.5 | Surface Fractions | 182 |
| | References | 185 |
| 11 | 2-D Grain Size Distributions | 187 |
| 11.1 | Measures for Grain Size | 187 |
| 11.2 | Mean Grain Size | 192 |
| 11.3 | Grain Size Distribution | 194 |
| 11.4 | Grain Size Mapping | 196 |
| | References | 199 |
| 12 | 3-D Grain Size | 201 |
| 12.1 | Random Sectioning of a Single Sphere | 201 |
| 12.2 | From 3-D Spheres to 2-D Sections | 205 |
| 12.2.1 | The Stereological Model | 205 |
| 12.2.2 | Four Typical Distributions | 207 |
| 12.3 | From 2-D Sections to 3-D Spheres | 207 |
| 12.4 | STRIPSTAR | 213 |
| 12.4.1 | How to Run STRIPSTAR | 214 |
| 12.5 | Practical Applications | 215 |
| 12.5.1 | Particles in a Matrix | 216 |
| 12.5.2 | Crystalline Aggregates | 217 |
| 12.5.3 | Shortcuts | 219 |
| 12.5.4 | The Influence of Shape: How Random is Random? | 221 |
| 12.5.5 | Error Estimation | 222 |
| 12.5.6 | Phi-Values and Logarithmic Binning | 222 |
| | References | 224 |
| 13 | Fractal Grain Size Distributions | 225 |
| 13.1 | Fragmentation in Nature and Experiment | 225 |
| 13.2 | Fragmenting the Cube | 227 |
| 13.2.1 | The Fractal Model for Sectioning | 228 |
| 13.2.2 | Fractal Dimensions | 229 |
| 13.2.3 | Fragmentation Numbers $F > 8$ or $F < 8$ | 231 |
| 13.2.4 | Continuous Fragmentation | 232 |
| 13.3 | Fragmentation Matrix | 233 |
| 13.3.1 | Deriving the Fractal Dimension from the Matrix | 234 |
| 13.3.2 | Fractal Dimension from the Matrix and from Grain Size Analysis | 239 |

| | | |
|--------|---|-----|
| 13.4 | Visualizing Grain Size Distributions | 241 |
| 13.4.1 | Preparing the Bitmap | 242 |
| 13.4.2 | Gauss Filtering | 243 |
| 13.4.3 | Converting the Matrix to the Fractal Dimension | 245 |
| 13.5 | Examples | 249 |
| | References | 249 |

Part IV Quantifying Shape and Orientation

| | | |
|-----------|--|------------|
| 14 | Particle Fabrics | 253 |
| 14.1 | Projections of a Single Ellipse | 254 |
| 14.2 | Projections of Non-elliptical Shapes | 255 |
| 14.3 | Best-Fit Ellipses and Convex Hulls | 256 |
| 14.4 | Projections of Sets of Ellipses | 261 |
| 14.5 | PAROR | 263 |
| 14.5.1 | How to Run PAROR | 264 |
| 14.5.2 | The Monitor Printout File | 265 |
| 14.5.3 | The B(α) File | 268 |
| 14.5.4 | The Axes Orientation File | 269 |
| 14.5.5 | The Particle Data File | 270 |
| 14.6 | PAROR Analysis of Particles in a Matrix | 270 |
| 14.7 | PAROR Analysis of Crystalline Aggregates | 272 |
| 14.8 | PAROR Analysis of Surfaces | 274 |
| 14.9 | Restoring the Input | 276 |
| 14.10 | PAROR Analysis Within Image SXM | 279 |
| | References | 280 |
| 15 | Surface Fabrics | 283 |
| 15.1 | Projection of Line Segments | 283 |
| 15.2 | Straight Line Segments | 284 |
| 15.3 | SURFOR | 285 |
| 15.3.1 | How to Run SURFOR | 287 |
| 15.3.2 | The Monitor Printout File | 287 |
| 15.3.3 | The A(α) File | 289 |
| 15.3.4 | The Surface Orientation File | 289 |
| 15.3.5 | The Characteristic Shape File | 289 |
| 15.4 | SURFOR Analysis of Lines Segments | 289 |
| 15.5 | SURFOR Analysis of Closed Outlines | 293 |
| 15.6 | SURFOR Versus PAROR Analysis | 294 |
| 15.7 | SURFOR Analysis of Incomplete Outlines | 297 |
| 15.8 | SURFOR Analysis of Open Lines | 298 |
| 15.9 | SURFOR Analysis Within Image SXM | 301 |
| | References | 303 |
| 16 | Strain Fabrics | 305 |
| 16.1 | Fabrics and Strain | 305 |
| 16.1.1 | Strain Markers | 305 |
| 16.1.2 | The Geometry of Strain | 306 |
| 16.2 | Measuring Strain with SURFOR | 308 |
| 16.3 | Testing for Strain | 312 |

| | | |
|-------------------------------------|--|------------|
| 16.4 | Practical Examples | 314 |
| 16.5 | SURFOR and PAROR Versus the $R_f-\phi$ Method | 317 |
| | References | 320 |
| 17 | Shape Descriptors | 323 |
| 17.1 | Shape Descriptors | 323 |
| 17.1.1 | Deviation from the Circular Form: Classical Shape Factors | 324 |
| 17.1.2 | Aspect Ratios | 326 |
| 17.1.3 | Convexity: Concavity | 328 |
| 17.1.4 | Excess Perimeter and Defect Area | 329 |
| 17.1.5 | Angularity | 331 |
| 17.2 | iSHAPES | 335 |
| 17.2.1 | How to Run iSHAPES | 335 |
| 17.3 | Manual and Automatic Digitization | 337 |
| 17.4 | Applications of iSHAPES | 339 |
| 17.4.1 | Fault Rock Microstructures | 339 |
| 17.4.2 | Grain Boundary Migration Microstructures | 342 |
| 17.4.3 | Annealing Microstructures | 344 |
| | References | 347 |
| Part V Spatial Relationships | | |
| 18 | Spatial Distributions | 351 |
| 18.1 | Basic Concepts | 351 |
| 18.1.1 | Spatial Distributions | 352 |
| 18.1.2 | Random Mixing | 354 |
| 18.1.3 | Volume Model and Surface Model | 356 |
| 18.2 | What to Measure | 356 |
| 18.3 | Test Samples | 357 |
| 18.4 | Analysis of a Polyphase Material | 359 |
| 18.4.1 | Focusing on One Phase | 361 |
| 18.4.2 | Selecting Two Phases | 363 |
| 18.5 | Errors | 365 |
| 18.6 | Orientation Dependent Analysis | 366 |
| | References | 368 |
| 19 | Spatial Frequencies | 369 |
| 19.1 | Spatial Frequencies | 369 |
| 19.2 | Fourier Transforms | 372 |
| 19.2.1 | One-Dimensional Fourier Transform | 372 |
| 19.2.2 | Two-Dimensional Fourier Transform | 373 |
| 19.2.3 | Discrete Fourier Transforms | 373 |
| 19.2.4 | Fast Fourier Transform | 375 |
| 19.3 | Interpreting Fourier Transform Images | 376 |
| 19.4 | Frequency Filtering | 377 |
| 19.4.1 | Selecting Frequencies | 378 |
| 19.4.2 | High-Pass and Low-Pass Filtering | 379 |
| 19.5 | Practical Applications | 385 |
| | References | 388 |

| | | |
|--|--|-----|
| 20 | Autocorrelation Function | 389 |
| 20.1 | Principles of Autocorrelation | 389 |
| 20.1.1 | Mathematical Definition | 390 |
| 20.1.2 | Autocorrelation Function of Single Shapes . . . | 391 |
| 20.1.3 | Autocorrelation Function of Sets of Shapes . . . | 392 |
| 20.2 | Analysis of Autocorrelation Functions | 397 |
| 20.3 | Practical Applications of Autocorrelation Functions . . . | 398 |
| 20.3.1 | Lazy ACF Tiling Macro | 400 |
| 20.3.2 | Bulk ACF | 402 |
| 20.3.3 | Local ACFs | 403 |
| 20.4 | Autocorrelation Functions and Strain Analysis | 405 |
| 20.4.1 | Heterogeneous Strain | 405 |
| 20.4.2 | Autocorrelation of Center Points | 407 |
| 20.4.3 | Deformation and Reaction | 408 |
| | References | 409 |
| Part VI Orientation Imaging | | |
| 21 | Crystal Orientation and Interference Color | 413 |
| 21.1 | Basic Concepts | 414 |
| 21.2 | Interference Colors | 417 |
| 21.2.1 | Birefringence | 417 |
| 21.2.2 | Optical Path | 418 |
| 21.2.3 | Spectra of Interference Colors | 419 |
| 21.2.4 | Color from Spectra | 421 |
| 21.2.5 | First-Order Colors and Section Thickness | 421 |
| 21.2.6 | Adding the Wave Plate | 422 |
| 21.3 | The Crystallographic Color Space | 425 |
| 21.3.1 | Polstacks | 426 |
| 21.3.2 | Polstack Sections | 426 |
| 21.4 | Color to Monochrome | 428 |
| 21.4.1 | Finding the Best Filter | 429 |
| 21.4.2 | Resolving the Azimuth | 431 |
| 21.4.3 | Resolving the Inclination | 433 |
| 21.5 | LUTs for CIP | 437 |
| 21.5.1 | Converting Intensity to Inclination | 437 |
| | References | 438 |
| 22 | Computer-Integrated Polarization Microscopy | 439 |
| 22.1 | How CIP Works: The Basic Idea | 441 |
| 22.2 | Acquire the Input | 443 |
| 22.2.1 | The Structure of the Input Stack | 444 |
| 22.2.2 | The Micrographs | 445 |
| 22.2.3 | Circular Polarization | 450 |
| 22.3 | Prepare the Input Stack | 451 |
| 22.4 | Pre-process the Input Stack | 456 |
| 22.4.1 | Calibration Files | 456 |
| 22.4.2 | Image Calibration | 457 |
| 22.4.3 | Lighting and Background Corrections | 457 |
| 22.4.4 | Section Thickness | 457 |

| | | |
|-----------|---|------------|
| 22.5 | Do the CIP | 460 |
| 22.6 | Viewing the Result | 467 |
| 22.7 | Pole Figures | 469 |
| 22.8 | Refining the Calculation | 469 |
| | References | 475 |
| 23 | Orientation and Misorientation Imaging | 477 |
| 23.1 | Orientation Imaging: Changing the Colors | 477 |
| 23.2 | Using EBSD Input | 480 |
| 23.2.1 | Full Texture Versus c-Axis | 480 |
| 23.2.2 | Euler Angles to c-Axes | 480 |
| 23.3 | Masking | 481 |
| 23.3.1 | Selecting Regions | 481 |
| 23.3.2 | Selecting Minerals | 487 |
| 23.4 | Misorientation Imaging | 487 |
| 23.4.1 | Principal Misorientations | 488 |
| 23.4.2 | Misorientation with Respect to Reference Direction | 488 |
| 23.4.3 | From Misorientation to Orientation | 488 |
| 23.4.4 | Misorientation Profiles | 490 |
| 23.5 | Segmentation in Orientation Space | 493 |
| 23.5.1 | Grain Boundaries and Sub-grain Boundaries | 494 |
| 23.5.2 | Flat Grains | 497 |
| 23.6 | Orientation Tracking | 497 |
| 23.6.1 | Texture Domains | 498 |
| 23.6.2 | Texture Domains of a Low-Strain Sample | 498 |
| 23.6.3 | Texture Domains of a High-Strain Sample | 501 |
| 23.6.4 | Domain Grain Size | 503 |
| 23.7 | Orientation Gradient Imaging | 506 |
| 23.7.1 | Orientation Gradients | 506 |
| 23.7.2 | Orientation Gradient Density | 506 |
| 23.7.3 | Sharp Boundaries | 507 |
| 23.8 | Texture-Dependent Shape Analysis | 509 |
| | References | 512 |
| | Index | 515 |



<http://www.springer.com/978-3-642-10342-1>

Image Analysis in Earth Sciences
Microstructures and Textures of Earth Materials
Heilbronner, R.; Barrett, S.
2014, XIX, 520 p. 596 illus., 257 illus. in color.,
Hardcover
ISBN: 978-3-642-10342-1