

---

# Contents

List of Acronyms.....	xxi
<b>1 Introduction.....</b>	<b>1</b>
1.1 Purpose of this Book .....	1
1.2 Systems and Key Input Variables.....	2
1.3 Problem-solving Methods.....	6
1.3.1 What Is “Six Sigma”? .....	7
1.3.2 What Is “Lean Manufacturing”? .....	10
1.3.3 What Is the “Theory of Constraints”? .....	10
1.3.4 What Is the “Theory of Constraints Lean Six Sigma”?...	10
1.4 History of “Quality” and Six Sigma .....	11
1.4.1 History of Management and Quality .....	11
1.4.2 History of Documentation and Quality .....	15
1.4.3 History of Statistics and Quality .....	15
1.4.4 The Six Sigma Movement.....	18
1.5 The Culture of Discipline .....	19
1.6 Real Success Stories .....	21
1.7 Overview of this Book.....	22
Problems .....	23
References.....	27

---

## Part I Statistical Quality Control

---

<b>2 Statistical Quality Control and Six Sigma .....</b>	<b>31</b>
2.1 Introduction .....	31
2.2 Method Names as Buzzwords .....	32
2.3 Where Methods Fit into Projects .....	33
2.4 Organizational Roles and Methods.....	35
2.5 Specifications: Non-conforming vs Defective.....	36
2.6 Standard Operating Procedures (SOPs).....	38
2.6.1 Proposed SOP Process .....	39
2.6.2 Measurement SOPs .....	42
Problems .....	42
References.....	46

<b>3</b>	<b>Define Phase and Strategy</b> .....	47
3.1	Introduction .....	47
3.2	Systems and Subsystems .....	48
3.3	Project Charters .....	49
3.3.1	Predicting Expected Profits.....	51
3.4	Strategies for Project Definition .....	53
3.4.1	Bottleneck Subsystems.....	53
3.4.2	Go-no-go Decisions .....	54
3.5	Methods for Define Phases.....	55
3.5.1	Pareto Charting .....	55
3.5.2	Benchmarking .....	58
3.6	Formal Meetings.....	60
3.7	Significant Figures.....	62
3.8	Summary .....	65
	Problems .....	67
	References.....	75
<b>4</b>	<b>Measure Phase and Statistical Charting</b> .....	77
4.1	Introduction .....	77
4.2	Evaluating Measurement Systems .....	78
4.2.1	Types of Gauge R&R Methods.....	79
4.2.2	Gauge R&R: Comparison with Standards.....	80
4.2.3	Gauge R&R (Crossed) with Xbar & R Analysis.....	83
4.3	Measuring Quality Using SPC Charting.....	87
4.3.1	Concepts: Common Causes and Assignable Causes .....	88
4.4	Commonality: Rational Subgroups, Control Limits, and Startup .....	89
4.5	Attribute Data: <i>p</i> -Charting.....	91
4.6	Attribute Data: Demerit Charting and <i>u</i> -Charting .....	96
4.7	Continuous Data: Xbar & R Charting .....	100
4.7.1	Alternative Continuous Data Charting Methods .....	106
4.8	Summary and Conclusions .....	107
	Problems .....	109
	References.....	119
<b>5</b>	<b>Analyze Phase</b> .....	121
5.1	Introduction .....	121
5.2	Lean Production.....	121
5.2.1	Process and Value Stream Mapping.....	122
5.2.2	5S .....	125
5.2.3	Kanban .....	126
5.2.4	Poka-Yoke.....	126
5.3	The Toyota Production System .....	127
5.4	Process Flow and Spaghetti Diagrams .....	128
5.5	Cause and Effect Matrices .....	131
5.6	Design of Experiments and Regression (Preview) .....	133
5.7	Failure Mode and Effects Analysis.....	135
5.9	Summary .....	138

Problems .....	139
References.....	148
<b>6 Improve or Design Phase.....</b>	<b>149</b>
6.1 Introduction .....	149
6.2 Informal Optimization.....	150
6.3 Quality Function Deployment (QFD).....	151
6.4 Formal Optimization.....	154
6.5 Summary .....	156
Problems .....	157
References.....	161
<b>7 Control or Verify Phase.....</b>	<b>163</b>
7.1 Introduction .....	163
7.2 Control Planning.....	164
7.3 Acceptance Sampling .....	167
7.3.1 Single Sampling .....	168
7.3.2 Double Sampling.....	169
7.4 Documenting Results.....	171
7.5 Summary .....	172
Problems .....	173
Reference .....	177
<b>8 Advanced SQC Methods .....</b>	<b>179</b>
8.1 Introduction .....	179
8.2 EWMA Charting for Continuous Data .....	180
8.3 Multivariate Charting Concepts.....	183
8.4 Multivariate Charting (Hotelling's $T^2$ Charts) .....	186
8.5 Summary .....	190
Problems .....	190
References.....	191
<b>9 SQC Case Studies.....</b>	<b>193</b>
9.1 Introduction .....	193
9.2 Case Study: Printed Circuit Boards .....	193
9.2.1 Experience of the First Team .....	195
9.2.2 Second Team Actions and Results .....	197
9.3 Printed Circuitboard: Analyze, Improve, and Control Phases....	199
9.4 Wire Harness Voids Study .....	202
9.4.1 Define Phase .....	203
9.4.2 Measure Phase.....	203
9.4.3 Analyze Phase.....	205
9.4.4 Improve Phase.....	206
9.4.5 Control Phase .....	206
9.5 Case Study Exercise .....	207
9.5.1 Project to Improve a Paper Air Wings System.....	208
9.6 Summary .....	212

Problems .....	213
References.....	215
<b>10 SQC Theory.....</b>	<b>217</b>
10.1 Introduction .....	217
10.2 Probability Theory.....	218
10.3 Continuous Random Variables.....	221
10.3.1 The Normal Probability Density Function.....	224
10.3.2 Defects Per Million Opportunities .....	230
10.3.3 Independent, Identically Distributed and Charting .....	231
10.3.4 The Central Limit Theorem.....	234
10.3.5 Advanced Topic: Deriving $d_2$ and $c_4$ .....	237
10.4 Discrete Random Variables .....	238
10.4.1 The Geometric and Hypergeometric Distributions .....	240
10.5 Xbar Charts and Average Run Length.....	243
10.5.1 The Chance of a Signal .....	243
10.5.2 Average Run Length .....	245
10.6 OC Curves and Average Sample Number .....	247
10.6.1 Single Sampling OC Curves .....	248
10.6.2 Double Sampling.....	249
10.6.3 Double Sampling Average Sample Number .....	250
10.7 Summary .....	251
Problems .....	252
References.....	255

**Part II Design of Experiments (DOE) and Regression**

<b>11 DOE: The Jewel of Quality Engineering .....</b>	<b>259</b>
11.1 Introduction .....	259
11.2 Design of Experiments Methods Overview.....	260
11.3 The Two-sample T-test Methodology and the Word “Proven” ..	261
11.4 T-test Examples .....	264
11.5 Randomization Testing and Paired T-testing.....	267
11.6 ANOVA for Two Sample T-tests.....	271
11.7 Full Factorials.....	275
11.8 Randomization and Evidence .....	277
11.9 Errors from DOE Procedures.....	278
11.10 Summary .....	280
Problems .....	282
Reference .....	287
<b>12 DOE: Screening Using Fractional Factorials .....</b>	<b>289</b>
12.1 Introduction .....	289
12.2 Standard Screening Using Fractional Factorials.....	290
12.3 Screening Examples .....	296

12.4	Method Origins and Alternatives.....	301
12.4.1	Origins of the Arrays.....	301
12.4.2	Alternatives to the Methods in this Chapter.....	303
12.5	Standard vs One-factor-at-a-time Experimentation.....	305
12.6	Summary .....	307
	Problems .....	307
	References.....	313
<b>13</b>	<b>DOE: Response Surface Methods.....</b>	<b>315</b>
13.1	Introduction .....	315
13.2	Design Matrices for Fitting RSM Models .....	316
13.3	One-shot Response Surface Methods .....	318
13.4	One-shot RSM Examples .....	321
13.5	Creating 3D Surface Plots in Excel .....	328
13.6	Sequential Response Surface Methods.....	329
13.7	Origin of RSM Designs and Decision-making.....	334
13.7.1	Origins of the RSM Experimental Arrays.....	334
13.7.2	Decision Support Information (Optional).....	337
13.8	Appendix: Additional Response Surface Designs.....	340
13.9	Summary .....	345
	Problems .....	345
	References.....	349
<b>14</b>	<b>DOE: Robust Design.....</b>	<b>351</b>
14.1	Introduction .....	351
14.2	Expected Profits and Control-by-noise Interactions.....	352
14.3	Robust Design Based on Profit Maximization .....	355
14.4	Extended Taguchi Methods.....	362
14.5	Literature Review and Methods Comparison.....	366
14.6	Summary .....	368
	Problems .....	368
	References.....	370
<b>15</b>	<b>Regression.....</b>	<b>373</b>
15.1	Introduction .....	373
15.2	Single Variable Example.....	374
15.2.1	Demand Trend Analysis.....	375
15.2.2	The Least Squares Formula.....	375
15.3	Preparing “Flat Files” and Missing Data.....	376
15.4	Evaluating Models and DOE Theory .....	378
15.4.1	Variance Inflation Factors and Correlation Matrices .....	379
15.4.2	Normal Probability Plots and Other “Residual Plots”.....	381
15.4.3	Summary Statistics.....	386
15.5	Analysis of Variance Followed by Multiple T-tests.....	389
15.6	Regression Modeling Flowchart.....	392

15.7	Categorical and Mixture Factors (Optional).....	397
15.7.1	Regression with Categorical Factors.....	398
15.7.2	DOE with Categorical Inputs and Outputs.....	399
15.7.3	Recipe Factors or “Mixture Components”.....	400
15.8	Summary.....	401
	Problems.....	402
	References.....	408
<b>16</b>	<b>Advanced Regression and Alternatives.....</b>	<b>409</b>
16.1	Introduction.....	409
16.2	Generic Curve Fitting.....	409
16.2.1	Curve Fitting Example.....	410
16.3	Kriging Model and Computer Experiments.....	411
16.3.1	Design of Experiments for Kriging Models.....	412
16.3.2	Fitting Kriging Models.....	412
16.3.3	Kriging Single Variable Example.....	415
16.4	Neural Nets for Regression Type Problems.....	415
16.5	Logistics Regression and Discrete Choice Models.....	421
16.5.1	Design of Experiments for Logistic Regression.....	423
16.5.2	Fitting Logit Models.....	424
16.6	Summary.....	427
	Problems.....	427
	References.....	428
<b>17</b>	<b>DOE and Regression Case Studies.....</b>	<b>431</b>
17.1	Introduction.....	431
17.2	Case Study: the Rubber Machine.....	431
17.2.1	The Situation.....	431
17.2.2	Background Information.....	432
17.2.3	The Problem Statement.....	432
17.3	The Application of Formal Improvement Systems Technology.....	433
17.4	Case Study: Snap Tab Design Improvement.....	437
17.5	The Selection of the Factors.....	440
17.6	General Procedure for Low Cost Response Surface Methods.....	441
17.7	The Engineering Design of Snap Fits.....	441
17.8	Concept Review.....	445
17.9	Additional Discussion of Randomization.....	446
17.10	Summary.....	448
	Problems.....	449
	References.....	451
<b>18</b>	<b>DOE and Regression Theory.....</b>	<b>453</b>
18.1	Introduction.....	453
18.2	Design of Experiments Criteria.....	454
18.3	Generating “Pseudo-Random” Numbers.....	455
18.3.1	Other Distributions.....	457

18.3.2	Correlated Random Variables .....	459
18.3.3	Monte Carlo Simulation (Review) .....	460
18.3.4	The Law of the Unconscious Statistician .....	461
18.4	Simulating T-testing .....	462
18.4.1	Sample Size Determination for T-testing .....	465
18.5	Simulating Standard Screening Methods .....	467
18.6	Evaluating Response Surface Methods .....	469
18.6.1	Taylor Series and Reasonable Assumptions .....	469
18.6.2	Regression and Expected Prediction Errors .....	471
18.6.3	The EIMSE Formula .....	474
18.7	Summary .....	480
	Problems .....	481
	References .....	483

---

### Part III Optimization and Strategy

---

<b>19</b>	<b>Optimization and Strategy .....</b>	<b>487</b>
19.1	Introduction .....	487
19.2	Formal Optimization .....	488
19.2.1	Heuristics and Rigorous Methods .....	491
19.3	Stochastic Optimization .....	493
19.4	Genetic Algorithms .....	495
19.4.1	Genetic Algorithms for Stochastic Optimization .....	495
19.4.2	Populations, Cross-over, and Mutation .....	496
19.4.3	An Elitist Genetic Algorithm with Immigration .....	497
19.4.4	Test Stochastic Optimization Problems .....	498
19.5	Variants on the Proposed Methods .....	498
19.6	Appendix: C Code for “Toycoolga” .....	500
19.7	Summary .....	504
	Problems .....	504
	References .....	506
<b>20</b>	<b>Tolerance Design .....</b>	<b>507</b>
20.1	Introduction .....	507
20.2	Summary .....	509
	Problems .....	509
	Reference .....	509
<b>21</b>	<b>Design for Six Sigma .....</b>	<b>511</b>
21.1	Introduction .....	511
21.2	Design for Six Sigma (DFSS) .....	511
21.3	Implementation .....	513
	Problems .....	516
	References .....	518

- 22 Lean Sigma Project Design** ..... 519
  - 21.1 Introduction ..... 519
  - 21.2 Literature Review ..... 520
  - 21.3 Reverse Engineering Six Sigma ..... 521
  - 21.4 Uncovering and Solving Optimization Problems ..... 523
  - 21.5 Future Research Opportunities ..... 527
    - 21.5.1 New Methods from Stochastic Optimization ..... 527
    - 21.5.2 Meso-analyses of Project Databases ..... 529
    - 21.5.3 Test Beds and Optimal Strategies ..... 530
  - Problems ..... 531
  - References..... 532
  
- Glossary** ..... 535
  
- Problem Solutions** ..... 543
  
- Index** ..... 565





<http://www.springer.com/978-1-84882-999-2>

Introduction to Engineering Statistics and Lean Sigma  
Statistical Quality Control and Design of Experiments  
and Systems

Allen, T.T.

2010, XXIII, 572 p., Hardcover

ISBN: 978-1-84882-999-2