
Contents

List of Acronyms.....	xxi
1 Introduction.....	1
1.1 Purpose of this Book	1
1.2 Systems and Key Input Variables.....	2
1.3 Problem-solving Methods.....	6
1.3.1 What Is “Six Sigma”?	7
1.3.2 What Is “Lean Manufacturing”?	10
1.3.3 What Is the “Theory of Constraints”?	10
1.3.4 What Is the “Theory of Constraints Lean Six Sigma”?...	10
1.4 History of “Quality” and Six Sigma	11
1.4.1 History of Management and Quality	11
1.4.2 History of Documentation and Quality	15
1.4.3 History of Statistics and Quality	15
1.4.4 The Six Sigma Movement.....	18
1.5 The Culture of Discipline	19
1.6 Real Success Stories	21
1.7 Overview of this Book.....	22
Problems	23
References.....	27

Part I Statistical Quality Control

2 Statistical Quality Control and Six Sigma	31
2.1 Introduction	31
2.2 Method Names as Buzzwords	32
2.3 Where Methods Fit into Projects	33
2.4 Organizational Roles and Methods.....	35
2.5 Specifications: Non-conforming vs Defective.....	36
2.6 Standard Operating Procedures (SOPs).....	38
2.6.1 Proposed SOP Process	39
2.6.2 Measurement SOPs	42
Problems	42
References.....	46

3	Define Phase and Strategy	47
3.1	Introduction	47
3.2	Systems and Subsystems	48
3.3	Project Charters	49
3.3.1	Predicting Expected Profits.....	51
3.4	Strategies for Project Definition	53
3.4.1	Bottleneck Subsystems.....	53
3.4.2	Go-no-go Decisions	54
3.5	Methods for Define Phases.....	55
3.5.1	Pareto Charting	55
3.5.2	Benchmarking	58
3.6	Formal Meetings.....	60
3.7	Significant Figures.....	62
3.8	Summary	65
	Problems	67
	References.....	75
4	Measure Phase and Statistical Charting	77
4.1	Introduction	77
4.2	Evaluating Measurement Systems	78
4.2.1	Types of Gauge R&R Methods.....	79
4.2.2	Gauge R&R: Comparison with Standards.....	80
4.2.3	Gauge R&R (Crossed) with Xbar & R Analysis.....	83
4.3	Measuring Quality Using SPC Charting.....	87
4.3.1	Concepts: Common Causes and Assignable Causes	88
4.4	Commonality: Rational Subgroups, Control Limits, and Startup.....	89
4.5	Attribute Data: <i>p</i> -Charting.....	91
4.6	Attribute Data: Demerit Charting and <i>u</i> -Charting	96
4.7	Continuous Data: Xbar & R Charting	100
4.7.1	Alternative Continuous Data Charting Methods	106
4.8	Summary and Conclusions	107
	Problems	109
	References.....	119
5	Analyze Phase	121
5.1	Introduction	121
5.2	Lean Production.....	121
5.2.1	Process and Value Stream Mapping.....	122
5.2.2	5S	125
5.2.3	Kanban	126
5.2.4	Poka-Yoke.....	126
5.3	The Toyota Production System	127
5.4	Process Flow and Spaghetti Diagrams	128
5.5	Cause and Effect Matrices	131
5.6	Design of Experiments and Regression (Preview)	133
5.7	Failure Mode and Effects Analysis.....	135
5.9	Summary	138

Problems	139
References.....	148
6 Improve or Design Phase.....	149
6.1 Introduction	149
6.2 Informal Optimization.....	150
6.3 Quality Function Deployment (QFD).....	151
6.4 Formal Optimization.....	154
6.5 Summary	156
Problems	157
References.....	161
7 Control or Verify Phase.....	163
7.1 Introduction	163
7.2 Control Planning.....	164
7.3 Acceptance Sampling	167
7.3.1 Single Sampling	168
7.3.2 Double Sampling.....	169
7.4 Documenting Results.....	171
7.5 Summary	172
Problems	173
Reference	177
8 Advanced SQC Methods	179
8.1 Introduction	179
8.2 EWMA Charting for Continuous Data	180
8.3 Multivariate Charting Concepts.....	183
8.4 Multivariate Charting (Hotelling's T^2 Charts)	186
8.5 Summary	190
Problems	190
References.....	191
9 SQC Case Studies.....	193
9.1 Introduction	193
9.2 Case Study: Printed Circuit Boards	193
9.2.1 Experience of the First Team	195
9.2.2 Second Team Actions and Results	197
9.3 Printed Circuitboard: Analyze, Improve, and Control Phases	199
9.4 Wire Harness Voids Study	202
9.4.1 Define Phase	203
9.4.2 Measure Phase.....	203
9.4.3 Analyze Phase.....	205
9.4.4 Improve Phase.....	206
9.4.5 Control Phase	206
9.5 Case Study Exercise	207
9.5.1 Project to Improve a Paper Air Wings System.....	208
9.6 Summary	212

Problems 213
 References..... 215

10 SQC Theory..... 217

10.1 Introduction 217

10.2 Probability Theory..... 218

10.3 Continuous Random Variables 221

10.3.1 The Normal Probability Density Function 224

10.3.2 Defects Per Million Opportunities 230

10.3.3 Independent, Identically Distributed and Charting 231

10.3.4 The Central Limit Theorem..... 234

10.3.5 Advanced Topic: Deriving d_2 and c_4 237

10.4 Discrete Random Variables 238

10.4.1 The Geometric and Hypergeometric Distributions 240

10.5 Xbar Charts and Average Run Length..... 243

10.5.1 The Chance of a Signal 243

10.5.2 Average Run Length 245

10.6 OC Curves and Average Sample Number 247

10.6.1 Single Sampling OC Curves 248

10.6.2 Double Sampling..... 249

10.6.3 Double Sampling Average Sample Number 250

10.7 Summary 251

Problems 252

References..... 255

Part II Design of Experiments (DOE) and Regression

11 DOE: The Jewel of Quality Engineering 259

11.1 Introduction 259

11.2 Design of Experiments Methods Overview..... 260

11.3 The Two-sample T-test Methodology and the Word “Proven”.. 261

11.4 T-test Examples 264

11.5 Randomization Testing and Paired T-testing..... 267

11.6 ANOVA for Two Sample T-tests 271

11.7 Full Factorials..... 275

11.8 Randomization and Evidence 277

11.9 Errors from DOE Procedures..... 278

11.10 Summary 280

Problems 282

Reference 287

12 DOE: Screening Using Fractional Factorials 289

12.1 Introduction 289

12.2 Standard Screening Using Fractional Factorials..... 290

12.3 Screening Examples 296

12.4	Method Origins and Alternatives.....	301
12.4.1	Origins of the Arrays.....	301
12.4.2	Alternatives to the Methods in this Chapter.....	303
12.5	Standard vs One-factor-at-a-time Experimentation.....	305
12.6	Summary	307
	Problems	307
	References.....	313
13	DOE: Response Surface Methods.....	315
13.1	Introduction	315
13.2	Design Matrices for Fitting RSM Models	316
13.3	One-shot Response Surface Methods	318
13.4	One-shot RSM Examples	321
13.5	Creating 3D Surface Plots in Excel	328
13.6	Sequential Response Surface Methods.....	329
13.7	Origin of RSM Designs and Decision-making.....	334
13.7.1	Origins of the RSM Experimental Arrays.....	334
13.7.2	Decision Support Information (Optional).....	337
13.8	Appendix: Additional Response Surface Designs.....	340
13.9	Summary	345
	Problems	345
	References.....	349
14	DOE: Robust Design.....	351
14.1	Introduction	351
14.2	Expected Profits and Control-by-noise Interactions.....	352
14.3	Robust Design Based on Profit Maximization	355
14.4	Extended Taguchi Methods.....	362
14.5	Literature Review and Methods Comparison.....	366
14.6	Summary	368
	Problems	368
	References.....	370
15	Regression.....	373
15.1	Introduction	373
15.2	Single Variable Example.....	374
15.2.1	Demand Trend Analysis.....	375
15.2.2	The Least Squares Formula.....	375
15.3	Preparing “Flat Files” and Missing Data.....	376
15.4	Evaluating Models and DOE Theory	378
15.4.1	Variance Inflation Factors and Correlation Matrices	379
15.4.2	Normal Probability Plots and Other “Residual Plots”...	381
15.4.3	Summary Statistics.....	386
15.5	Analysis of Variance Followed by Multiple T-tests.....	389
15.6	Regression Modeling Flowchart.....	392

- 15.7 Categorical and Mixture Factors (Optional)..... 397
 - 15.7.1 Regression with Categorical Factors..... 398
 - 15.7.2 DOE with Categorical Inputs and Outputs..... 399
 - 15.7.3 Recipe Factors or “Mixture Components” 400
- 15.8 Summary 401
- Problems 402
- References..... 408

- 16 Advanced Regression and Alternatives..... 409**
 - 16.1 Introduction 409
 - 16.2 Generic Curve Fitting 409
 - 16.2.1 Curve Fitting Example 410
 - 16.3 Kriging Model and Computer Experiments..... 411
 - 16.3.1 Design of Experiments for Kriging Models 412
 - 16.3.2 Fitting Kriging Models..... 412
 - 16.3.3 Kriging Single Variable Example..... 415
 - 16.4 Neural Nets for Regression Type Problems 415
 - 16.5 Logistics Regression and Discrete Choice Models..... 421
 - 16.5.1 Design of Experiments for Logistic Regression..... 423
 - 16.5.2 Fitting Logit Models 424
 - 16.6 Summary 427
 - Problems 427
 - References..... 428

- 17 DOE and Regression Case Studies 431**
 - 17.1 Introduction 431
 - 17.2 Case Study: the Rubber Machine 431
 - 17.2.1 The Situation..... 431
 - 17.2.2 Background Information 432
 - 17.2.3 The Problem Statement..... 432
 - 17.3 The Application of Formal Improvement Systems Technology. 433
 - 17.4 Case Study: Snap Tab Design Improvement 437
 - 17.5 The Selection of the Factors 440
 - 17.6 General Procedure for Low Cost Response Surface Methods.... 441
 - 17.7 The Engineering Design of Snap Fits 441
 - 17.8 Concept Review..... 445
 - 17.9 Additional Discussion of Randomization 446
 - 17.10 Summary 448
 - Problems 449
 - References..... 451

- 18 DOE and Regression Theory 453**
 - 18.1 Introduction 453
 - 18.2 Design of Experiments Criteria 454
 - 18.3 Generating “Pseudo-Random” Numbers 455
 - 18.3.1 Other Distributions..... 457

18.3.2	Correlated Random Variables	459
18.3.3	Monte Carlo Simulation (Review)	460
18.3.4	The Law of the Unconscious Statistician	461
18.4	Simulating T-testing	462
18.4.1	Sample Size Determination for T-testing	465
18.5	Simulating Standard Screening Methods	467
18.6	Evaluating Response Surface Methods	469
18.6.1	Taylor Series and Reasonable Assumptions	469
18.6.2	Regression and Expected Prediction Errors	471
18.6.3	The EIMSE Formula	474
18.7	Summary	480
	Problems	481
	References	483

Part III Optimization and Strategy

19	Optimization and Strategy	487
19.1	Introduction	487
19.2	Formal Optimization	488
19.2.1	Heuristics and Rigorous Methods	491
19.3	Stochastic Optimization	493
19.4	Genetic Algorithms	495
19.4.1	Genetic Algorithms for Stochastic Optimization	495
19.4.2	Populations, Cross-over, and Mutation	496
19.4.3	An Elitist Genetic Algorithm with Immigration	497
19.4.4	Test Stochastic Optimization Problems	498
19.5	Variants on the Proposed Methods	498
19.6	Appendix: C Code for “Toycoolga”	500
19.7	Summary	504
	Problems	504
	References	506
20	Tolerance Design	507
20.1	Introduction	507
20.2	Summary	509
	Problems	509
	Reference	509
21	Design for Six Sigma	511
21.1	Introduction	511
21.2	Design for Six Sigma (DFSS)	511
21.3	Implementation	513
	Problems	516
	References	518

- 22 Lean Sigma Project Design** 519
 - 21.1 Introduction 519
 - 21.2 Literature Review 520
 - 21.3 Reverse Engineering Six Sigma 521
 - 21.4 Uncovering and Solving Optimization Problems 523
 - 21.5 Future Research Opportunities 527
 - 21.5.1 New Methods from Stochastic Optimization 527
 - 21.5.2 Meso-analyses of Project Databases 529
 - 21.5.3 Test Beds and Optimal Strategies 530
 - Problems 531
 - References..... 532

- Glossary** 535

- Problem Solutions** 543

- Index** 565



<http://www.springer.com/978-1-84882-999-2>

Introduction to Engineering Statistics and Lean Sigma
Statistical Quality Control and Design of Experiments
and Systems

Allen, T.

2010, XXIII, 572 p., Hardcover

ISBN: 978-1-84882-999-2