

Contents

1 Silica Glass Optical Fiber and Fiber Fuse	1
1.1 Introduction	1
1.2 Silica Glass Optical Fibers	3
1.3 Fiber Fuse Propagation and Damage Left Behind	6
1.4 Safeguard Technologies	9
1.5 Conclusion	12
References	12
2 Fiber Fuse Propagation Modes	17
2.1 Introduction	17
2.2 In Situ Observation of Fiber Fuse Propagation	18
2.3 Void Track Variation with Pump Power	20
2.4 Precise Measurement of Propagation Speed	22
2.5 Summary	24
References	24
3 Periodic Void Formation	25
3.1 Introduction	25
3.2 Void Formation Process in Cylindrical Mode	25
3.3 Cladding Mode Self-pumping of Confined Plasma	29
3.4 Periodic Void Formation in Unstable Mode	32
3.5 Summary	34
References	34
4 Delayed Response of Silica Melt to Pump Modulation	37
4.1 Introduction	37
4.2 Self-pumping Modulation	38
4.3 Pump Power Modulation	38
4.4 Waveguide Modulation	43
4.5 Summary	47
References	47

5 Conclusion	49
Appendix A: Comparison with Bulk Silica Glass Modification by Continuous-Wave Laser	51
Appendix B: Fiber Fuse in Materials Other than Silica Glass	53
Index	57



<http://www.springer.com/978-4-431-54576-7>

Fiber Fuse

Light-Induced Continuous Breakdown of Silica Glass
Optical Fiber

Todoroki, S.-i.

2014, XIII, 58 p. 51 illus., 16 illus. in color., Softcover

ISBN: 978-4-431-54576-7